











オーバーハング用役物一覧表

		オーバーハング 3 5		オーバーハング 4 5	
出隅	L=100×100mm	01-M07	入数 5個	01-M08	入数 5個
					
入隅	L=100×100mm	01-M14	入数 5個	01-M15	入数 5個
					
ジョイント	L=50mm	01-M12	入数 10個	01-M13	入数 10個
					
エンドキャップ (左右セット)	L=30mm	01-M16	入数 5セット	01-M17	入数 5セット
左  右 